

EUCLEIA TabScan S7C快速指南(英文)			
编辑时间:	2019-1-3	版本:	S7C-UG-001
设计:	蒋小勇	审核:	Tony
印刷要求:	彩色CMYK印刷, 过哑胶, 五折页		
尺寸材质:	尺寸 : 90x145mm 材料 : 128g双铜纸		

TabScan S7C

Automotive Intelligent Diagnostic Tool

Quick Start Guide

Warm Notice :

Please register and update to enjoy the latest software, and visit website: www.eucleia.net for more detailed news.

• Packing Content

Part	Name	Part	Name
	S7C		Wiping Cloth
	Main Cable		Quick Start Guide
	USB Cable		Plastic Handbag
	AC/DC Adapter		

• Diagnostic Tablet

- Front View -

- Back View -

- Top View -

Notoice:

Please make sure the battery percentage is more than 35% before update the syetem.

- Wi-Fi Connection
 - Once power on the device, then unlock the menu.

- Unlock Menu -

- Slide the Screen -

- System Menu -

- Confirm Wi-Fi is available, select "Setting" - "Wi-Fi".

- Setting -

- Wi-Fi -

- Switch on the Wi-Fi, select available Wi-Fi and input correct password.

- Switch on Wi-Fi -

- Input Password -

- Customer Register and Log in
 - Select APP "TabScan" - "Update" go to register menu.

- Click Update -

- Click Register -

- Input all required information to finish the registration process.

- Input Details -

- log in -

- System Update
 - Please make sure Wi-Fi is connected before updating.
 - Make sure the battery percentage is more than 50%.
 - Select App "TabScan" - "Update" (if not registered, please back to step 2).

- Click Update -

- Log in -

- System update (click "update" or "update all"), and waiting for installation(if system is latest version, then skip this).

- Click Update -

- Installing the System -

- APP Update
 - Please make sure Wi-Fi is connected before the update.
 - Make sure battery percentage is more than 35%.
 - Select update or update all.

- Update or Update All -

- Downloading -

- Click the Install -

- Waiting for Installation -

5. Vehicle Software Update

- Please make sure Wi-Fi is connected before the update.
- Make sure battery percentage is more than 35%.
- Select update or update all.

- Select Update -

- Update or Update All -

6. Firmware Update

- Please make sure Wi-Fi is connected before the update.
- Make sure battery percentage is more than 50%.
- Select "wiScan Manager", click update, waiting for the installation.

- Click "wiScan Manager" -

- Click Update -

• S7C Operation Menu

1. S7C Homepage Introduction

Product Model

Time
Battery Percentage
Bluetooth
Wi-Fi Connection
Real-Time Voltage
Vehicle Connection

2. Diagnosis Page Introduction

Guided Region

Car Region

3. Guided Region

Vehicle Region

Homepage
Record Data
Screenshot
Return
Diagnostic Records
Positioning
Car Search
Vehicle Connection
Real-Time Voltage

4. Diagnostic Software Selection in Land Rover and Toyota.

- Select "Diagnosis" in Homepage, then search the car model according to keywords or slide screen to find Land Rover.

- Click Land Rover -

- Click Toyota -

- Input the VIN NUM or Click "Manual" -

- Select "Diagnosis" in Homepage, then search the car model according to keywords or slide screen to find Toyota.

- Click Toyota -

- "Automatic" or "Manually" -

• Diagnostic Procedure

- Power on TabScan.

- Connect the main cable with diagnostic interface on TabScan and fasten the screws.

- Connect the main cable (16PIN) with car's diagnostic interface, normally it located under the dashboard.

4. Once connect the TabScan with car, please confirm the upper right connection display V and real-time voltage is workable, then start the diagnose.

5. After S7C is ready, then start using: click "Diagnosis", "Service" or "Coding" to diagnose.

- Update or Update All -

- Downloading -

- Click the Install -

- Waiting for Installation -

5. Vehicle Software Update

- Please make sure Wi-Fi is connected before the update.
- Make sure battery percentage is more than 35%.
- Select update or update all.

- Select Update -

- Update or Update All -

6. Firmware Update

- Please make sure Wi-Fi is connected before the update.
- Make sure battery percentage is more than 50%.
- Select "wiScan Manager", click update, waiting for the installation.

- Click "wiScan Manager" -

- Click Update -

• S7C Operation Menu

1. S7C Homepage Introduction

Product Model

Time
Battery Percentage
Bluetooth
Wi-Fi Connection
Real-Time Voltage
Vehicle Connection

2. Diagnosis Page Introduction

Guided Region

Car Region

3. Guided Region

Vehicle Region

Homepage
Record Data
Screenshot
Return
Diagnostic Records
Positioning
Car Search
Vehicle Connection
Real-Time Voltage

4. Diagnostic Software Selection in Land Rover and Toyota.

- Select "Diagnosis" in Homepage, then search the car model according to keywords or slide screen to find Land Rover.

- Click Land Rover -

- Click Toyota -

- Input the VIN NUM or Click "Manual" -

- Select "Diagnosis" in Homepage, then search the car model according to keywords or slide screen to find Toyota.

- Click Toyota -

- "Automatic" or "Manually" -

• Diagnostic Procedure

- Power on TabScan.

- Connect the main cable with diagnostic interface on TabScan and fasten the screws.

- Connect the main cable (16PIN) with car's diagnostic interface, normally it located under the dashboard.

4. Once connect the TabScan with car, please confirm the upper right connection display V and real-time voltage is workable, then start the diagnose.

5. After S7C is ready, then start using: click "Diagnosis", "Service" or "Coding" to diagnose.